

Stan of Utah

DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director

JOHN R. BAZA Division Director

Inspection Report Minerals Regulatory Program

Report Date: August 10, 2006

Mine Name: Lakeside Mountain

Operator Name: Chemical Lime Company of AZ

Inspector(s): Dan Smith Other Participants: None

Mine Status: REC

Permit number: M0450038

Inspection Date: 08/09/2006

Supervisor

Time:

Weather:

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds			
2. Public Safety (shafts, adits, trash, signs, highwalls)			
3. Protection of Drainages / Erosion Control			
4. Deleterious Material			
5. Roads (maintenance, surfacing, dust control, safety)			
6. Concurrent Reclamation			
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)			
8. Water Impoundments			
9. Soils			
10. Revegetation			
11. Air Quality			
12. Other			

Purpose of Inspection:

Site has not been inspected in a very long time.

Directions to Site:

Take Lakeside exit from I-80 and head North.

Inspection Summary:

Site appears to be completely reclaimed. Over grown pre-existing roads are the only things that remain.

Conclusions and Recommendations:

Recommend that the primary inspector review this mine.


Inspector's Signature


ds

cc: Operator

(Agency)

Attachment: Map & Photos








Figure 4 ... Surface Layout

